

# Version 4.1.0 Release Notes

AutoSPRINK VR4 v4.1.0

Total: 12

SEi		Subtotal: 12
<b>Issue ID:</b>	<b>DT9884</b>	
<b>Title:</b>	<u>Cylinder tool needs to be available to non-CPW users</u>	
<b>Issue ID:</b>	<b>DT9845</b>	
<b>Title:</b>	<u>Plot sheet - Fields not filling in</u>	
<b>Issue ID:</b>	<b>DT9837</b>	
<b>Title:</b>	<u>The do not print fitting option is also not printing sprinklers.</u>	
<b>Issue ID:</b>	<b>DT9777</b>	
<b>Title:</b>	<u>Gemlist - Export errors</u>	
<b>Issue ID:</b>	<b>DT9755</b>	
<b>Title:</b>	<u>Hydraulics - Numbers change</u>	
<b>Issue ID:</b>	<b>DT9746</b>	
<b>Title:</b>	<u>undo a relocated pipe - crash</u>	
<b>Issue ID:</b>	<b>DT9449</b>	
<b>Title:</b>	<u>Remote area boundary auto-draw fails with heads set to "rect" coverage.</u>	
<b>Issue ID:</b>	<b>DT9395</b>	
<b>Title:</b>	<u>Detail Quantity on Material Summary</u>	
<b>Issue ID:</b>	<b>DT9392</b>	
<b>Title:</b>	<u>ASVR4 Help Menu with two bad links</u>	
<b>Issue ID:</b>	<b>DT9313</b>	
<b>Title:</b>	<u>Sprinkler head counts don't match</u>	
<b>Issue ID:</b>	<b>DT9294</b>	
<b>Title:</b>	<u>Sprinkler Heads - Stocklist too many</u>	
<b>Issue ID:</b>	<b>DT9250</b>	
<b>Title:</b>	<u>GEM list export - clarify outlet size</u>	